2023 Annual Performance Report Municipal Stormwater Management System Environmental Compliance Approval Number 101-S701 Schedule E Section 5.2 Report



For the period of January 1, 2023 to December 31, 2023

Prepared for the Corporation of the Town of Grand Valley by R.J. Burnside & Associates Limited



2023 Annual Performance Report For an Authorized Municipal Stormwater Management System CLI-ECA No. 101-S701 Schedule E Section 5.2 Report Town of Grand Valley

This annual report was prepared in accordance with the requirements of the Consolidated Linear Infrastructure Environmental Compliance Approval (CLI-ECA) No. 101-S701 for a Municipal Stormwater Management System issued for the Town of Grand Valley for the period from January 1, 2023 to December 31, 2023. The CLI-ECA for the Town of Grand Valley was issued by the Ministry of the Environment, Climate Change and Parks (MECP) on December 22, 2022.

The first set of inspections under this CLI-ECA were undertaken at the beginning of November 2023. Corrective actions based on the inspections are expected to be completed in 2024 and will be reported on in the 2024 annual report.

This report meets the requirements of Sections 5.2 and 5.3 of the CLI-ECA which are repeated in bold text below, with the annual report content following each bold text entry:

Submit the Annual Report to the MECP Director on or before April 30th of each year (Section 5.2.1):

This annual report for the year 2023 is submitted prior to April 30, 2024.

Include a summary and interpretation of all monitoring data with an overview of the condition and operational performance of the Authorized System and any Adverse Effects on the Natural Environment (Section 5.2.2):

This is a future requirement. A Monitoring Plan which may produce data for evaluating the system performance, has yet to be developed under the requirements of the CLI-ECA.

Include a summary and interpretation of environmental trends based on all monitoring information and data for the previous five (5) years (Section 5.2.3):

This is a future requirement. An evaluation of environmental trends related to the Authorized System will be prepared in future annual reports once five years of data is compiled after a Monitoring Plan is developed.

Include a summary of any operating problems encountered and corrective actions taken (Section 5.2.4), and

Include a summary all inspections, maintenance, and repairs carried out on any major structure, equipment, apparatus, mechanism or thing forming part of the Authorized System (Clause 5.2.5):

Continues on next page

Stormwater Management (SWM) Facility and ID No.	Summary of Issues	Summary of Corrective Action
Mount Haven (3885)	 <u>Operational Issues:</u> Sediment accumulation, overgrown vegetation and erosion at pond inlet pipe Condition of rip rap erosion protection at pond inlet to be determined Access road in an easement from the street is not defined Pond forebay and wetland cell were dry <u>Structure Inspection Issues:</u> No warning sign in place No guard located on top of headwalls Potential obstruction of pond outlet pipe or drain pipe Grating not in place on pond outlet pipe or drain pipe Orifice plate is missing in outlet control MH Broken valve box on pond drain valve Unknown condition of drain valve located in control MH At the sag location on Mt. Haven Road, the grates on 3-DICB's are missing grate retainer clips 	Inspections were completed in the fall of 2023. Corrective actions are expected in 2024.
WWTP (5278)	 <u>Operational Issues:</u> Pond bottom heavily overgrown with cattails and reeds preventing inspection of pond bottom Water level could not be measured in the pond due to vegetation growth Access to perforated outlet pipe blocked with vegetation <u>Structure Inspection Issues:</u> Orifice plate in control MH is out of place Drain valve is open with flow passing through the valve 	Inspections were completed in the fall of 2023. Corrective actions are expected in 2024.

Continues on next page

Stormwater Management (SWM) Facility and ID No.	Summary of Issues	Summary of Corrective Action
Taylor Drive (8316)	 <u>Operational Issues:</u> Excessive woody growth and reeds at and above water level Phragmites invasive plants at water level and on slopes Outlet structure partially blocked with vegetation reducing outflow Some algae growth Scour hole, erosion and sedimentation at pond inlet headwall and inlet to forebay Displaced rip rap at pond inlet headwall 	Inspections were completed in the fall of 2023. Corrective actions are expected in 2024.
	 <u>Structure Inspection Issues:</u> Minor leakage of outlet structure Minor corrosion of orifice plate Unknown condition of 2 drain valves in maintenance MH Railing at headwall to be upgraded to guards 	
Mayberry Drive (8317)	 Operational Issues: Ducks present in permanent pool area Outlet structures including grating substantially blocked with vegetation, filter cloth and clear stone reducing outflow Significant algae growth Permanent pool level lower than expected Minor amounts of debris within pond block Scour hole, erosion and sedimentation at west pond inlet headwall and inlet to forebay Displaced rip rap at west pond inlet headwall At west inlet headwall, grade is too low behind the headwall/wingwalls and should be raised to the level of top of wall Displaced rip rap at east pond inlet headwall Condition of trees around and in pond block to be reviewed. 	Inspections were completed in the fall of 2023. Corrective actions are expected in 2024.
	 <u>Structure Inspection Issues:</u> Unknown condition of drain valve located in the maintenance MH Minor crack in headwall above top of storm sewer at east inlet headwall Railing at headwalls to be upgraded to guards 	

Stormwater Management (SWM) Facility and ID No.	Summai	ry of Issues		Summary of Corrective Action
Ritchie Drive (8318)	 Mino struc Settle Exce head Soft Plant conn 	ement around DICB outlet structure essive vegetation blocking south po wall. Condition of rip rap unknown spots in bottom of dry pond ted trees continue to have tree ties ected to support stakes	ond inlet 1.	Inspections were completed in the fall of 2023. Corrective actions are expected in 2024.
	• NO W	/arning sign present		
Jenkins Street (8350)	 Winter outfa Invasarea Lowarea Lowarea Botto 	nal Issues: er sand obstructing overflow weir a ill swale sive phragmites vegetation in dry s flow channel is not defined or has mulated sediment om of pond is soft and saturated <u>e Inspection Issues:</u> /arning sign present		Inspections were completed in the fall of 2023. Corrective actions are expected in 2024.
Stormwater Out	fall	Summary of Operational and Inspection Issues	Sum	mary of Corrective Action
Outfalls to receivers as on Maps identified in T of the CLI-ECA		Not inspected in 2023.		ntenance/repair work ted in 2023.
Stormwater Colle System	ction	Summary of Operational and Inspection Issues	Sum	mary of Corrective Action
Sewer system (pipes & structures) as noted or identified in Table B1 o CLI-ECA	n Maps	No CCTV work or formal inspection in 2023.		ent removed from all asins between May
Melody Lane Oil-Grit S (OGS1)	eparator	No formal inspection. Sump observed during sediment removal.		ent removed between 2-26, 2023
Monty Avenue Oil-Grit Separator (OGS2)		No formal inspection. Sump observed during sediment removal.		ent removed between 2-26, 2023

Include a summary of the calibration and maintenance carried out on all monitoring equipment (Clause 5.2.6):

There is no monitoring equipment presently installed in the Authorized System.

Include a summary of any complaints related to the Sewage Works Received during the reporting period and any steps taken to address the complaints (Clause 5.2.7):

Complaint Description	Action Taken
Town staff report no complaints were received	N/A

Include a summary of all Alterations to the Authorized System within the reporting period that are authorized by this Approval including a list of Alterations that pose a Significant Drinking Water Threat (Clause 5.2.8):

Summary of Alteration to the Authorized System	Does Alteration pose a Significant Drinking Water Threat (Yes/No)
Mayberry Phase 3B Subdivision: Storm Sewers,	No
OGSs, and Stormwater Management Facilities	
152 Main Street North: Storm Sewers, OGS,	No
Superpipe	

Report Date	Summary of Spill or Discharge Event
Town staff report no spills or abnormal events were observed or reported	N/A

nclude a summary of actions taken, including tim erformance of any aspect of the Authorized Syste	
Actions Taken to Improve/Correct System Performance	Timeline of Actions
N/A	N/A

Actions Recommended from 2022 Reporting Year	Status
N/A – This is the first Annual Performance Report	

Make this Annual Report available, on request and without charge, to members of the public who are served by the Authorized System (Clause 5.3.1):

This Annual Report is available to members of the public who are served by the Authorized System by contacting the Municipal Office or by accessing the Municipal website.

Make this Annual Report available, by June 1st of the same reporting year, to members of the public without charge by publishing the report on the Internet if the Owner maintains a website on the Internet (Clause 5.3.2):

This Annual Report will be made available to members of the public by June 1, 2024, by accessing the Municipal website:

https://www.townofgrandvalley.ca/en/our-services/water-and-waste-water.aspx